

16 OCTOBER, 1991

BULLETIN.019

WELDMATIC 160SI CP101 WELDING TRANSFORMER

There appears to be some confusion when replacing faulty main transformers in the CP101.

In the early machines, the CP101-13 horizontally mounted transformer was used. This was later changed to the new type CP101-32 vertically mounted transformer.

The old style CP101-13 transformer is still available from the factory should you need to replace a faulty one.

Alternatively, a CP101-32 can be fitted, however, the rectifier must be relocated to allow the transformer to fit in. This usually takes more time to complete the job.

For machine reference, the new transformer (mounted vertically), commenced with serial number 101-13-1.