

## **CP38-16 WIRE/GAS CONTROL PCB**

Due to “motor cogging” occurring under certain conditions at low motor speed a change to the CP38-16 PCB has been made.

Change 100 kohm resistor R4 to 47 kohm resistor.