

27 MARCH, 1987

BULLETIN.002

W1-33/1 GAS VALVE

Due to the problem of gas valves not operating reliably when high gas flow rates are set, a decision has been made to change the coil of the Goyen gas valve from 32 Vdc to 24 Vdc.

The part number of the complete gas valve remains unchanged.

UPDATE 16 NOVEMBER, 1994

The Goyen gas valve has now been replaced in production by an ASCO valve, W.I.A. part number CP101-0/18.