

10 JULY, 1990

BULLETIN.005


WELDARC 150: MC84 TIGARC 140: MC86 MC84 AND 86-11 RESISTOR VALUES

On the MC84-11 PCB's, the values of the resistors R8 and R9 have now been changed:

R8 resistor was 27K ohms, is now 22K ohms.
R9 resistor was 18K ohms, is now 15K ohms.

On the MC86-11 PCB's, the resistor values are still the same, being:

R8 and R9 resistors are both 10K ohm.



				WELDING INDUSTRIES OF AUSTRALIA	
				112 Daws Road, Melrose Park, S.A.5039	
				TITLE	
				P.C.BOARD ASSEMBLY	
B.	10/7/90	ec	RESISTOR VALUES R8 & R9 CHANGED C/N 1054	DRAWN	DRAWING No.
A			ISSUE FOR MANUFACTURE	M.W.	
ISSUE	DATE	CHKD.	REVISION	DATE	
				6-7-90	MC84-11