

18 JULY, 1990

BULLETIN.006

WELDMATIC 205S: CP102
CP101-12/2 CAPACITORS

Due to problems experienced with the above power capacitors failing in service, the three capacitor (15,000uF 40V) set has been replaced with a four capacitor (10,000uF 63V) set.

The replacement kit is part number CP102-37 and includes four of the new capacitors (CP102-12/8), mounting hardware and fitting instructions.