

SEPTEMBER, 1994

BULLETIN.015

## WELDMATIC FABRICATOR: CP33 CONTACTORS

Primary contactor CP2-0/13, which had a 110 Vac coil, has now been replaced by a CP38-0/10, which has a 32 Vac coil.

This is to keep the control voltages going to the wire feeders within the 32 Vac "Extra-low Level" limits.

This change was introduced with revision B of the CP33, released in March 1993.