


3 OCTOBER, 1991

BULLETIN.016

WELDMATIC 205S: CP102 CP102-11 TRIAC CONTROL PCB

Some early model machines using this PCB, were found to have problems with resistor R15 breaking down, causing no output power.

This resistor has now been replaced with a version that has a higher voltage rating, the part number now being CP102-11/3 (390 Ohm 1W 500V).



TRIAC CONTROL BOARD CP102-11