

3 OCTOBER, 1991

BULLETIN.017


WELDARC 140: MC84 WELDARC 12P: MC85
MC84-11 TRIAC PCB

Diode D1 has now been changed from CP101-11/10 (1N4007) to a MC84-11/3 (BYW56).

Refer to attached component overlay.

UPDATE SEPTEMBER '94

Refer also to Service Bulletin 111 for information regarding failures of diode D1.



				WELDING INDUSTRIES OF AUSTRALIA	
				112 Daws Road, Melrose Park. S.A.5039	
				TITLE	
				P.C.BOARD ASSEMBLY	
B	10/7/90	gc	RESISTOR VALUES R8 & R9 CHANGED C/N 1054	DRAWN	DRAWING No.
A			ISSUE FOR MANUFACTURE	M.W.	
ISSUE	DATE	CHKD.	REVISION	DATE	
				6-7-90	MC84-11