

3 MARCH, 1992

BULLETIN.020A

AM69 OVERLOAD DEVICE

It has been found that in the earlier AM69-C2 circuits, that the relay being used allowed a 'spike' from the 110 Vac contactor control circuit to be 'induced' into Pin 6 of the 741 Op Amp, which then destroyed that component.

The circuit has now been re-designed to incorporate a relay with better contact isolation which effectively overcomes this fault.

The new circuit is called an AM69-C3.