

3 SEPTEMBER, 1992

BULLETIN.100

PART NUMBER CP38-13/1 - C/N 1142

Part Number CP34-11/4 metal oxide varistors used for sipmos over voltage protection are no longer available. An alternative component is available - part number CP38-13/1 Transorb 1.4KE91A.

The transorb device provides faster transient voltage clipping capabilities and can be expected to further reduce sipmos failure.

Parts list affected:

CP34-11 main sipmos assembly now issue 3
CP34-12 background sipmos assembly now issue 4

CP36-11 main sipmos assembly now issue B
CP36-13 background sipmos assembly now issue B

Drawings affected:

CP34-11 assembly drawing now issue B
CP34-11/C1 circuit diagram now issue B
CP34-12 assembly drawing now issue B

CP36-11 assembly drawing now issue B
CP36-11/C1 circuit drawing now issue B
CP36-13 assembly drawing now issue B