

24 OCTOBER, 1994

BULLETIN.117

## CP42-10 PRINTED CIRCUIT ASSEMBLY

A new revision of the CP42-10 is now in production which features a switch for the selection of arc starting mode.

) The slide switch is mounted on the circuit board and functions as below;

UP = 'Creep' mode (slow wire run-in)

DOWN = 'Standard' mode (fast wire run-in)

A description of this new switch function has been added to the CP42 owners manual dated 10/94.



GARY CHEESMAN

MARKETING MANAGER - EQUIPMENT

QUALITY WELDING PRODUCTS, SYSTEMS & SERVICE

UP = Creep mode  
Down = Standard mode

