

10 MAY, 1995

BULLETIN.124

SAF NERTAZIP

The high frequency board, part number 0408-3814 which is used in the SAF 215, 525 and 540 may be fitted with 5 off faulty HF coupling capacitors, value 0.022 mfd, 1.6kv.

The faulty items are colour blue, and at this time are to be replaced with an alternative brand component which is colour white, coded PS22nK CO 1.6K - 5A.

The faulty symptom is unreliable arc initiation. Although the potential for the fault exists in all of the above models, it is most common in the SAF 540.

No charge replacement capacitors for machines sold by WIA can be obtained from WIA Adelaide.

Note that we have been advised by SAF that future equipment deliveries may again include 'blue' capacitors, but that these devices are an approved type.



GARY CHEESMAN
MARKETING MANAGER - EQUIPMENT

QUALITY WELDING PRODUCTS, SYSTEMS & SERVICE