

15 JUNE, 1995

BULLETIN.128

DRIVE ROLLS ON MILLER 60 SERIES/CONSTRUCTOR WF60 FEEDERS

● If a customer is complaining of gear noise, or is finding red dust present in the 60 Series Feeder, it may be attributed to the old style 12 pitch carrier gears wearing prematurely. Miller now have a new style carrier gear available that incorporates a 24 pitch gear.

The part numbers for the new drive roll kits are MR172127 for the four roll kit, and MR172148 for the two roll kit. Both kits include the pinion gear.

Units effective with Serial Number KE756284 were manufactured with the new style gears.

smcintosh

per STEVE ROUSE
TECHNICAL MANAGER

QUALITY WELDING PRODUCTS, SYSTEMS & SERVICE