

27 August, 1998

BULLETIN #150

SYNCHRO-PULSE CDT 450**WELDING EPROMS #38009 & #38010**

There have been several cases recently where the Display EPROM in the CDT 450 has been updated to the latest version, following which the display does not work correctly.

It has been discovered that the latest Display EPROMs do not work when used together with older Welding EPROMs #38009 & #38010.

In this situation, the Welding EPROM must also be updated to the latest version - #38021.

WIA part number for Welding EPROM #38021 is CP38-3/50.



James Chin

Technical Service Co-ordinator - Marketing

QUALITY WELDING PRODUCTS, SYSTEMS AND SERVICES

The information provided in this sheet is accurate and reliable, however no warranty of accuracy or reliability is given and no responsibility arising in any other ways by errors or omissions is accepted