



03-04-2007

BULLETIN # 216

## **MC91-0, 92-0 & 93-0, MC100-0,101-0 & 102-0**

### NEW TOROID L0021

Service Bulletin #202 advised that 4 x L0006 toroids were being fitted to the output busbars. This was required to match the characteristics of the output rectifier. A larger toroid, part number L0021 is now used on each busbar, reducing the number of toroids back to one per busbar.

L0006 is now not available from WIA as a spare part; instead L0021 should be used.

The new toroid has been used in production starting with the following serial numbers:

Weldarc 125i M910C0307027001

Weldarc 145i M920C0307026001

Weldarc 165i M930C0307026001

Hugh Stewart,  
Technical Service Coordinator

---

*QUALITY WELDING PRODUCTS, SYSTEMS AND SERVICES*

The information provided in this sheet is accurate and reliable, however no warranty of accuracy or reliability is given and no responsibility arising in any other ways by errors or omissions is accepted. Any information involving mains or high voltage is intended for use by qualified electrical personnel only.